

Client Contact:

**Ms. Melissa Keithly
The Summit at Rock
Creek Homeowners
c/o Association &
Community
Management**

Services Provided:

- Analyzed Data
- Conducted
Subsurface
Exploration
- Observed
Construction and
Testing

Project Summary:

Cesare, Inc. (Cesare) analyzed data collected by other firms and conducted subsurface exploration of the site as part of a design-build project. Summit at Rock Creek is a subdivision in Superior, Colorado. During the construction phase of the project, Cesare observed the construction and testing, acting as a representative for the owner. Fifteen anchors and shotcrete panels were installed to stabilize the wall.

